

DEPARTMENT OF TRANSPORTATION -Toll Bridge Program

333 Burma Rd.
Oakland, CA 94607
(510) 622-5660, (510) 286-0550 fax



*Flex your power
Be energy efficient!*

November 23, 2009

Contract No. 04-0120F4
04-SF-80-13.2 / 13.9
Self-Anchored Suspension Bridge
Letter No. 05.03.08-000031

Michael Flowers
Project Executive
American Bridge/Fluor, A JV
375 Burma Road
Oakland, CA 94607

Dear Michael Flowers,

Grind Transverse Welds on OBG

Certain areas of the transverse seam weld joints on lifts 3 and 4 of the OBG have not been ground flush. These areas are depicted in the attached diagrams previously provided by ABF (it was unknown at the time these diagrams were prepared whether the areas designated "no access" were ground flush). You are hereby directed to grind these areas flush, including any portion of the areas designated "no access" that have subsequently been determined to not be ground flush, to allow for additional inspection.

Sincerely,

GARY PURSELL
Resident Engineer

cc: R. Morrow, P. Siegenthaler, D. Coe, S. Kennedy, G. Pursell, M. Wahbeh, T. Anziano, K.
Terpstra
File: 05.03.08